

## Orifice Replacement Chart

### R22 Only --- R410 Not yet available

(Used when installing 13 seer with older air handler that does not have TXV)

	Orifice	Part #
2TTB3018	0.049	RSR0065
2TTB3024	0.059	RSR0049
2TTB3030	0.067	RSR0025
2TTB3036	0.071	RSR0051
2TTB3042	0.080	RSR0029
2TTB3048	0.086	RSR0035
2TTB3060	TWE060D air handler has TXV	

2TWB3018	0.049	RSR0065
2TWB3024	0.059	RSR0049
2TWB3030	0.065	RSR0039
2TWB3036	0.073	RSR0026
2TWB3042	0.079	RSR0047
2TWB3048	0.083	RSR0052
2TWB3060	TWE060D air handler has TXV	

2TTR3018	0.049	RSR0065
2TTR3024	0.059	RSR0049
2TTR3030	0.067	RSR0025
2TTR3036	0.071	RSR0051
2TTR3042	0.080	RSR0029
2TTR3048	0.086	RSR0035
2TTR3060	TWE060D air handler has TXV	

2TWR3018	0.049	RSR0065
2TWR3024	0.059	RSR0049
2TWR3030	0.065	RSR0039
2TWR3036	0.073	RSR0026
2TWR3042	0.079	RSR0047
2TWR3048	0.083	RSR0052
2TWR3060	TWE060D air handler has TXV	